

652 Oliver Street Williamsport, PA. 17701 U.S.A.

Telephone +1 (877) 839-7878 (U.S. and Canada) Telephone +1 (570) 327-7222 (International)

Fax +1 (570) 327-7101

Email <u>Technicalsupport@lycoming.com</u>

www.lycoming.com

DATE:

## SERVICE INSTRUCTION

Service Instruction No. 1585A (Supersedes Service Instruction No. 1585)

Engineering Aspects are FAA Approved

SUBJECT: Oil Cooler Bypass Valve Assembly Replacement

December 1, 2023

MODELS AFFECTED: TEO-540-C1A

TIME OF COMPLIANCE: At owner's discretion

REASON FOR REVISION Revised the first paragraph and replacement instructions based on the option

to use either Oil Cooler Bypass Valve Assembly P/N 53E29909 or Oil Cooler

Bypass Valve Assembly P/N 53E22144

**NOTICE:** Incomplete review of all the information in this document can cause errors. Read the entire Service Instruction to make sure you have a complete understanding of the requirements.

Lycoming Engines has approved the use of either Oil Cooler Bypass Valve Assembly P/N 53E29909 or Oil Cooler Bypass Valve Assembly P/N 53E22144, to maintain optimum oil temperature of 185° F to 220° F (85° C to 104° C), depending upon varying ambient temperatures.

Lycoming Engines Oil Cooler Bypass Valve Assembly recommendations:

P/N 53E29909 – In areas where Outside Air Temperature (OAT) frequently prevents oil temperature from reaching and sustaining within the optimum temperature range.

P/N 53E22144 – In areas where Outside Air Temperature (OAT) allows the oil temperature to sustain within the optimum temperature range without exceeding the maximum temperature.

## If the Oil Cooler Bypass Valve Assembly Requires Replacement:

- 1. Remove the installed oil cooler bypass valve Assembly in accordance with instructions in Chapter 72-50 of the latest revision of the TEO-540-C1A Engine Maintenance Manual.
- 2. Install the appropriate oil cooler bypass valve Assembly in accordance with instructions in Chapter 72-50 of the latest revision of the TEO-540-C1A Engine Maintenance Manual.
- 3. Perform a post maintenance engine run-up and leak check. Correct any leaks.
- 4. Record the installation of bypass valve in engine maintenance records.

If you have any questions, contact Lycoming Technical Support by phone at 570-327-7222 or 877-839-7878 or email to Technical Support@lycoming.com.



ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR	1 of 1	A
11	19	2021	12	01	2023		