



652 Oliver Street  
Williamsport, PA. 17701 U.S.A.  
Telephone +1-877-839-7878 (U.S. and Canada)  
Telephone +1-570-323-7222 (International)  
Facsimile +1-570-327-7101  
Email [Technicalsupport@lycoming.com](mailto:Technicalsupport@lycoming.com)  
[www.lycoming.com](http://www.lycoming.com)

# SERVICE LETTER

Service Letter No. L299

January 5, 2026

TO: Owners and Operators of Lycoming IO-390-C3B6 Engine Models Installed on Cirrus Aircraft  
SUBJECT: Retirement of two configurations of IO-390-C3B6 engines

**NOTICE:** Incomplete review of all the information in this document can cause errors. Read the entire Service Letter to make sure you have a complete understanding of the requirements.

This Service Letter is to inform customers of the retirement of ENPL-RT11143 and ENPL-10944 configurations of engine model IO-390-C3B6. From the date of this Service Letter going forward these two engine configurations will be replaced by ENPL-RT11267. The new configuration will have improved throttle adjustment and throttle response.

At the owner's discretion:

- To configure your aircraft for the ENPL-RT11267 from an ENPL-RT10944, you must comply with the latest revision of Cirrus Service Bulletin SB2X-71-40 to upgrade to the LFR-BNRM10 fuel injection servo and SB2X-71-32R1 to remove the fuel pump cooling shroud.
- To configure your aircraft for the ENPL-RT11267 from an ENPL-RT11143, you must comply with the latest revision of Cirrus Service Bulletin SB2X-71-40 to upgrade to the LFR-BNRM10 fuel injection servo.

Contact Cirrus Aircraft for the latest revision of Cirrus Service Bulletin SB2X-71-40 or Cirrus Service Bulletin SB2X-71-40.

If you have any questions, contact Lycoming Technical Support by phone at 570-327-7222 or 877-839-7878 or email to [Technicalsupport@lycoming.com](mailto:Technicalsupport@lycoming.com).



General Aviation  
Manufacturers Association

ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR	1 of 1	--
01	05	26	--	--	--		