

652 Oliver Street Williamsport, PA. 17701 U.S.A.

Telephone +1-877-839-7878 (U.S. and Canada) Telephone +1-570-323-7222 (International)

Facsimile +1-570-327-7101

Email <u>Technicalsupport@lycoming.com</u>

www.lycoming.com

## SERVICE LETTER

Service Letter No. L289 March 02, 2022

TO: All Owners, Operators, and Maintenance Providers of Lycoming

Aircraft Engines

SUBJECT: Valve Spring Part Numbers

**NOTICE:** Incomplete review of all the information in this document can cause errors. Read the entire

Service Letter to make sure you have a complete understanding of the requirements.

Lycoming has released new valve springs with new part numbers that are interchangeable with the old valve springs. The chart below shows which valve springs are interchangeable. Part numbers listed together in a row are interchangeable with each other on the same engine.

Original Part and Color Code	New Part and Color Code	
LW-11795 Spring Valve Inner (BLUE)	17D29055 Spring Valve Inner (Orange)	
LW-11797 Spring Valve Inner (WHITE)	17D29057 Spring Valve Inner (GREEN)	
LW-11800 Spring Valve Outer (BLUE)	17D29060 Spring Valve Outer (ORANGE)	
LW-11796 Spring Valve Outer (WHITE)	17D29056 Spring Valve Outer (GREEN)	

**NOTICE:** Due to current supply chain challenges, customers should be aware that spare parts orders of valve springs may contain springs of 2 different colors/part numbers that are interchangeable with each other.

If you have any questions, contact Lycoming Technical Support by phone at 570-327-7222 or 877-839-7878 or email to <u>Technicalsupport@lycoming.com</u>.



	ISSUE	ED .	REVISED		PAGE NO.	REVISION	
MO	DAY	YEAR	MO	DAY	YEAR	1 of 1	
03	02	22					