



652 Oliver Street
 Williamsport, PA 17701 U.S.A.

Tel. 570-323-6181
 Fax. 570-327-7101
 www.lycoming.com

SERVICE INSTRUCTION

DATE: June 30, 2010

Service Instruction No. 1529A
 (Supersedes Service Instruction No. 1529)

Engineering Aspects are
 FAA (DER) Approved

SUBJECT: Hydraulic Lifter, Tappet Body and Valve Usage

MODELS AFFECTED: All Lycoming reciprocating aircraft engines.

TIME OF COMPLIANCE: As required for replacement.

This Service Instruction is being issued to inform owners and operators of a change to the following hydraulic lifter, tappet body and valve part numbers. This revision is issued to add two part numbers: 15B21318 (Hydraulic Tappet Body) and 78290 (Hydraulic Lifter Plunger Assembly). The succeeding part numbers have been manufactured to be equivalent to the previous part numbers and are singly interchangeable with the previous part numbers.

PREVIOUS PART NUMBER	DESCRIPTION	SUCCEEDING PART NUMBER
72877	BODY - HYDRAULIC TAPPET	15B26064
71105	TAPPET ASSY - VALVE	15B26091
LW-16812	LIFTER - HYDRAULIC	15B26090
LW-15861	LIFTER - HYDRAULIC	15B26088
LW-16586	LIFTER - HYDRAULIC	15B26089
15B21318	BODY - HYDRAULIC TAPPET	15B26262
78290	PLUNGER ASSY - HYDRAULIC LIFTER	15B26066



General Aviation
 Manufacturers Association

ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		
11	20	09	06	30	10	1 of 1	A

©2010 by Avco Corporation All Rights Reserved.

Lycoming Engines, a division of AVCO Corporation, Avco Corporation is a wholly owned subsidiary of Textron Inc.