



652 Oliver Street
 Williamsport, PA 17701 U.S.A.

Tel. 1-800-258-3279 (U.S. and Canada)
 Tel. 1-570-323-6181 (International)
 Fax. 1-570-327-7101
 www.lycoming.com

MANDATORY SERVICE BULLETIN

August 31, 2012

Supplement No. 1

To

Service Bulletin No. 543C

This supplement to Service Bulletin No. 543C is for clarification of Option 2 on Page 2: the new oil filter converter plate gasket does **not** have a pre-stamp of 543. There is **no** need to vibropeen 543 on the converter plate. The part number is visible with the plate installed.



General Aviation
 Manufacturers Association

ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		
08	31	12	--	--	--	1 of 1	C-Sup.1