

MANDATORY SERVICE BULLETIN

Supplement No. 1

To

Service Bulletin No. 573

March 16, 2007

Supplement No. 1 to Service Bulletin No. 573 is being issued to correct the serial number suffix of certain TIO-540-AJ1A engines.

On page 3, in Table 3 of Service Bulletin No. 573 the following TIO-540-AJ1A serial numbers should read as follows:

TIO-540-AJ1A

L-12487-61E
L-12492-61E
L-12505-61E
L-12510-61E
L-12511-61E
L-12516-61E
L-12518-61E
L-12535-61E
L-12537-61E
L-12539-61E
L-12542-61E
L-12546-61E