



652 Oliver Street  
Williamsport, PA 17701 U.S.A.  
Tel. 570-323-6181  
Fax. 570-327-7101  
www.lycoming.textron.com

# MANDATORY

# SERVICE BULLETIN

April 28, 2003

Supplement No. 1

To

Service Bulletin No. 547

The P/N 18M22676 connecting rod bearing is no longer available from Lycoming. It has been replaced by P/N LW-16143.

The sentence in the first paragraph of Service Bulletin No. 547 that calls out connecting rod bearings (P/N 18M22676) should read as follows:

Lycoming found no apparent operational or dimensional cause for the reported occurrences; however, in an effort to minimize any chance of an additional occurrence, Lycoming instituted a mandatory replacement program to equip the subject engines with new connecting rod bearings (P/N 18M22676 or **P/N LW-16143**) with increased durability.

The NOTE at the bottom of the page should read as follows:

**NOTE:** P/N 18M22676 or **P/N LW-16143** bearings and all parts necessary to change bearings are included in kit P/N 05K23068. When factory stock of P/N 18M22676 is depleted, only P/N LW-16143 will be included in kit P/N 05K23068. Connecting rod bearings must be used only in rod sets of identical part numbers.