



652 Oliver Street  
Williamsport, PA. 17701 U.S.A.

Tel. 1-800-258-3279  
Fax. 1-570-327-7101  
www.lycoming.com

# SERVICE INSTRUCTION

DATE: June 27, 2012 Service Instruction No. 1549  
Engineering Aspects are  
FAA Approved

SUBJECT: Notification of Approved Fuel Pump Plunger P/N 23D26777

MODELS AFFECTED: Engines that have Fuel Pump Plunger P/N 61544 installed.

TIME OF COMPLIANCE: At next engine overhaul, whenever fuel pump plunger appears damaged, or earlier at owner's discretion.

### NOTE

Incomplete review of all the information in this document can cause errors. Read the entire Service Instruction to make sure you have a complete understanding of the requirements.

This Service Instruction is notification that Fuel Pump Plunger P/N 23D26777 is an approved replacement for Fuel Pump Plunger P/N 61544.

### NOTE

The fuel pump plunger must be replaced at overhaul, unless otherwise shown in the latest revision of Service Bulletin No. 240.



ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR	1 of 1	-
06	27	12	--	--	--		