



652 Oliver Street  
 Williamsport, PA 17701 U.S.A.

Tel. 1-800-258-3279 (U.S. and Canada)

Tel. 1-570-323-6181 (International)

Fax. 1-570-327-7101

www.lycoming.com

# MANDATORY

# SERVICE BULLETIN

October 9, 2012

Supplement No. 1

To

Service Bulletin No. 603

This Supplement No. 1 is to clarify terms in the revised last paragraph of the NOTE on page 2 of Lycoming Engines' Service Bulletin No. 603, dated October 4.

Original NOTE in Service Bulletin No. 603:


### NOTE

If the magneto is functioning correctly, is affected by Slick SB1-12 and is within the Lycoming Engines warranty period, a warranty claim for removal and installation labor and freight charges for rework at Slick or **parts and** labor for point replacement plus labor for magneto removal and installation may be filed through an authorized Lycoming distributor. Labor will be paid in accordance with Lycoming Engines current Removal and Installation Labor and Allowance Guidebook.

In the last paragraph below in this Supplement No. 1, the words "parts and" have been removed.

### NOTE

If the magneto is functioning correctly, is affected by Slick SB1-12 and is within the Lycoming Engines warranty period, a warranty claim for removal and installation labor and freight charges for rework at Slick or labor for point replacement plus labor for magneto removal and installation may be filed through an authorized Lycoming distributor. Labor will be paid in accordance with Lycoming Engines current Removal and Installation Labor and Allowance Guidebook.

 <b>General Aviation Manufacturers Association</b>	ISSUED			REVISED			PAGE NO.	REVISION
	MO	DAY	YEAR	MO	DAY	YEAR	1 of 1	Sup. 1
	10	08	12	--	--	--		