

# **LYCOMING**

652 Oliver Street  
Williamsport, PA. 17701 U.S.A.

Telephone +1 (800) 258-3279 U.S. and Canada (Toll Free)  
Telephone +1 (570) 323-6181 (Direct)  
Facsimile +1 (570) 327-7101

www.lycoming.com

# SERVICE INSTRUCTION

March 19, 2013

Supplement No. 1

To

Service Instruction No. 1454A

This supplement corrects the Part Number in the following NOTE of Service Instruction No. 1454A dated February 25, 2011.

## NOTE

Before reusing Rocker Arm Assembly P/N LW-18790, refer to the latest revision of Lycoming Service Bulletin No. 477 (AD 87-10-06).



General Aviation  
Manufacturers Association

ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		
03	09	13	--	--	--	1 of 1	A-SUP 1

©2013 Avco Corporation All Rights Reserved.  
Lycoming Engines is a division of Avco Corporation.