

**LYCOMING**

A Textron Company

652 Oliver Street  
Williamsport, PA. 17701 U.S.A.

Tel. 570-323-6181

Fax. 570-327-7101

www.lycoming.com

# SERVICE INSTRUCTION

March 5, 1993

Supplement No. 1

To

Service Instruction No. 1029D

On page 7 of 9 of Service Instruction No. 1029D, the first sentence of step 8, should read as follows:

8. Using the same sequence as described in paragraphs 5 and 6, and shown in Figure 12, check all 1/2 inch nuts for tightness by bringing torque to 600 in. lb. (50 ft. lb.).



General Aviation  
Manufacturers Association

ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		
02	10	61	--	--	--	1 of 1	D-Sup 1