



652 Oliver Street
 Williamsport, PA. 17701 U.S.A.
 Telephone +1 (800) 258-3279 U.S. and Canada (Toll Free)
 Telephone +1 (800) 323-6181 International
 Facsimile +1 (570) 327-7101
 www.lycoming.com

SERVICE LETTER

Service Letter No. L258
 August 27, 2013

TO: All Lycoming Engine Owners, Operators, and Authorized Lycoming Distributors

SUBJECT: Part Number Supersedure for External Retaining Ring

NOTE

Incomplete review of all the information in this document can cause errors. Read the entire Service Letter to make sure you have a complete understanding of the requirements.

This Service Letter is to advise customers, operators and authorized Lycoming distributors that External Retaining Ring P/N MS16624-37 is superseded by P/N MS16624-2037 External Retaining Ring (zinc coated).



ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR	1 of 1	-----
08	27	13	--	--	--		