



652 Oliver Street
 Williamsport, PA. 17701 U.S.A.

Telephone +1 (800) 258-3279 (U.S. and Canada)
 Telephone +1 (570) 323-6181 (International)
 Facsimile +1 (570) 327-7101
 Email Technicalsupport@lycoming.com
 www.lycoming.com

SERVICE LETTER

Service Letter No. L272A
 (Supersedes Service Letter No. 272)
 November 21, 2017

TO: All Owners and Operators of Lycoming Aircraft Engines
 SUBJECT: Release of New Silicone Rocker Cover Gaskets

REASON FOR REVISION: Added new silicone gasket part number

NOTICE: Incomplete review of all the information in this document can cause errors. Read the entire Service Letter to make sure you have a complete understanding of the requirements.

This Service Letter identifies part numbers for silicone rocker cover gaskets (Table 1) as approved replacements for cork rocker cover gaskets.

NOTICE: A silicone rocker cover gasket can be reused if it is not damaged whereas a single-use cork gasket must be discarded and replaced after it has been removed from the engine.

To prevent leakage, be sure to use the **35 in.-lb.** (4.0 Nm) torque value for the rocker cover screws when a silicone gasket is installed and **not** the 50 in.-lb. (5.6 Nm) torque when a cork gasket is installed.

**Table 1
Rocker Cover Gaskets**

Silicone Gasket P/N	Cork Gasket P/N	Cylinder Type
06B26669	75906	Parallel Valve
06B26811	67193	Angle Valve - Down Exhaust
06B26813	71450	Angle Valve - Up Exhaust
06B28890	76036	Angle Valve – Down Exhaust



ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR	1 of 1	A
07	17	17	11	21	17		