



652 Oliver Street
 Williamsport, PA. 17701 U.S.A.
 Telephone +1-877-839-7878 (U.S. and Canada)
 Telephone +1-570-323-7222 (International)
 Fax +1-570-327-7101
 Email Technicalsupport@lycoming.com
www.lycoming.com

SERVICE LETTER

Service Letter No. L272B
 (Supersedes Service Letter No. 272A)
 February 14, 2024

TO: All Owners and Operators of Lycoming Aircraft Engines
 SUBJECT: Release of New Silicone Rocker Cover Gaskets

REASON FOR REVISION: Added reference to Service Instruction No. 1588

NOTICE: Incomplete review of all the information in this document can cause errors. Read the entire Service Letter to make sure you have a complete understanding of the requirements.

This Service Letter identifies part numbers for silicone rocker cover gaskets (Table 1) as approved replacements for cork rocker cover gaskets.

NOTICE: A silicone rocker cover gasket can be reused if it is not damaged whereas a single-use cork gasket must be discarded and replaced after it has been removed from the engine.

For rocker box cover installation, refer to the latest revision of Service Instruction No. 1588 for torque sequence and initial and final torque values.

**Table 1
Rocker Cover Gaskets**

Silicone Gasket P/N	Cork Gasket P/N	Cylinder Type
06B26669	75906	Parallel Valve
06B26811	67193	Angle Valve - Down Exhaust
06B26813	71450	Angle Valve - Up Exhaust
06B28890	76036	Angle Valve – Down Exhaust



ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR	1 of 1	B
07	17	17	02	14	24		