

652 Oliver Street Williamsport, PA. 17701 U.S.A.

Telephone +1-877-839-7878 (U.S. and Canada) Telephone +1-570-323-7222 (International)

Facsimile +1-570-327-7101

Email <u>Technicalsupport@lycoming.com</u>

www.lycoming.com

SERVICE LETTER

Service Letter No. L291 September 23, 2025

TO: All Owners and Operators of TIO-540-AK1A Engine Model

SUBJECT: Substitution of Turbocharger

NOTICE: Incomplete review of all the information in this document can cause errors. Read the entire

Service Letter to make sure you have a complete understanding of the requirements.

The purpose of this Service Letter is to communicate to the field the temporary use of turbocharger P/N 46C31588, with a stainless-steel turbine housing in place of turbocharger P/N 46C22924. A limited number of New, Rebuilt, or Overhauled TIO-540-AK1A engines were delivered from the Lycoming factory between October 10, 2023 and July 31, 2024 using Turbocharger P/N 46C31588, Model TAO411 (Hartzell P/N 466642-0008) as an alternate to the standard P/N 46C22924, Model TAO411 (Hartzell P/N 466642-0006).

Fit and function of turbocharger P/N 46C31588 is the same as turbocharger P/N 46C22924 and the same Instructions for Continued Airworthiness (ICA) apply. Operation of engines using turbocharger P/N 46C31588 is unchanged and will be performed in accordance with the existing applicable engine manuals and/or Pilots Operating Handbook (POH) or Airplane Flight Manual (AFM). The only difference is in weight, turbocharger P/N 46C31588 weighs 20.54 lbs. (9.32 kg) while turbocharger P/N 46C22924 weighs 18.00 lbs. (8.16 kg).

If you have any questions, contact Lycoming Technical Support by phone at 570-327-7222 or 877-839-7878 or by email to <u>Technicalsupport@lycoming.com</u>.



| ISSUED | | | REVISED | | | PAGE NO. | REVISION |
|--------|-----|------|---------|-----|------|----------|----------|
| MO | DAY | YEAR | MO | DAY | YEAR | 1 of 1 | |
| 09 | 23 | 2025 | | | | | |