



A Textron Company

652 Oliver Street
Williamsport, PA. 17701 U.S.A.

Tel. 570-323-6181
Fax. 570-327-7101
www.lycoming.com

SERVICE INSTRUCTION

DATE: November 20, 2009

Service Instruction No. 1529
Engineering Aspects are
FAA (DER) Approved

SUBJECT: Hydraulic Lifter, Tappet Body and Valve Usage

MODELS AFFECTED: All Lycoming reciprocating aircraft engines.

TIME OF COMPLIANCE: As required for replacement.

This Service Instruction is being issued to inform owners and operators of a change to the following hydraulic lifter, tappet body and valve part numbers. The succeeding part numbers have been manufactured to be equivalent to the previous part numbers and are singly interchangeable with the previous part numbers.

PREVIOUS PART NUMBER	DESCRIPTION	SUCCEEDING PART NUMBER
72877	BODY-HYDRAULIC TAPPET	15B26064
71105	TAPPET ASSY - VALVE	15B26091
LW-16812	LIFTER - HYDRAULIC	15B26090
LW-15861	LIFTER - HYDRAULIC	15B26088
LW-16586	LIFTER - HYDRAULIC	15B26089



ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR	1 of 1	--
11	20	09	--	--	--		