

 652 Oliver Street

 Williamsport, PA.
 17701
 U.S.A.

 Tel.
 570-323-6181

 Fax.
 570-327-7101

 www.lycoming. com

SERVICE INSTRUCTION

DATE:

August 26, 2010

Service Instruction No. 1204D (Supersedes Service Instruction No. 1065A and No. 1204C) Engineering Aspects are FAA (DER) Approved

SUBJECT: Exhaust Flange Gaskets

MODELS AFFECTED:

All Lycoming Engines using either V-Shaped Spiral Wound or Beaded Exhaust Flange Gaskets.

TIME OF COMPLIANCE: At overhaul or whenever exhaust flange gaskets are replaced.

Exhaust flange gaskets made of V-shaped, spiral-wound layers of stainless steel and either a non-asbestos filler or flexible graphite are available for all Lycoming engines using the two or three hole gasket design. See Figure 1. This gasket is resilient and automatically adjusts for mechanical compression, internal pressure variations, and temperature changes.

The flat, carbon-steel ring around the spiral windings centers the gasket and controls gasket compression when the exhaust manifold attaching bolts are tightened. In addition to superior sealing qualities, these gaskets are reusable when the exhaust manifold is loosened or removed. However, they must be replaced at overhaul.



Figure 1. V-Shaped Exhaust Flange Gasket Configuration

NOTE P/N LW-19296 is no longer available and has been replaced with P/N 77611.



General Aviation Manufacturers Association	ISSUED			REVISED			PAGE NO.	REVISION
	MO	DAY	YEAR	MO	DAY	YEAR	1 of 2	D
	03	17	78	08	26	10	1 01 2	
						0 2010 1	a	

© 2010 Avco Corporation. All rights reserved. Lycoming Engines is a division of Avco Corporation. Where beaded exhaust flange gaskets are used, they must be assembled (two each per exhaust port flange) with their beads interlocking. The flat side of the gasket must face toward the cylinder head and the raised or bead side, toward the exhaust stack. See Figure 2.

After initial installation, retorque the exhaust flange nuts after the first 25-hours of engine operation to allow for permanent seating of the beads. The beaded exhaust flange gasket can not be reused. Replace this beaded gasket with a new gasket after each removal.



Figure 2. Beaded Exhaust Flange Gasket Configuration

ISSUED			REVIS	ED	PAGE NO.	REVISION		
MO	DAY	YEAR	MO	DAY	YEAR	2 of 2	D	S.I. 1204
03	17	78	08	26	10	2 01 2		