



652 Oliver Street
 Williamsport, PA. 17701 U.S.A.
 Telephone +1 (800) 258-3279 (U.S. and Canada)
 Telephone +1 (570) 323-6181 (International)
 Facsimile +1 (570) 327-7101
 www.lycoming.com

SERVICE LETTER

Service Letter No. L255A
 (Supersedes Service Letter No. L255)
 May 13, 2016

TO: All Owners and Operators of Lycoming Piston Aircraft Engines
 SUBJECT: Approved diaphragm-type fuel pumps

NOTICE: Incomplete review of all the information in this document can cause errors. Read the entire Service Letter to make sure you have a complete understanding of the requirements.

An alternate diaphragm-type fuel pump P/N 62B26931 is approved as an equivalent replacement for the current fuel pump P/N LW-15473 except as noted in Table 1.

On the models listed in Table 1 use P/N LW-15473 only (fuel pump, dual diaphragm, high pressure).

**Table 1
Models Affected**

Model
HIO-360-D1A
HIO-360-G1A
O-540-L3C5D
TO-360-C1A6D
YO-235-EXP



General Aviation
Manufacturers Association

ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR	1 of 1	A
04	26	13	05	13	16		