



652 Oliver Street
 Williamsport, PA. 17701 U.S.A.
 Telephone +1 (800) 258-3279 U.S. and Canada (Toll Free)
 Telephone +1 (800) 323-6181 International
 Facsimile +1 (570) 327-7101
 www.lycoming.com

SERVICE LETTER

Service Letter No. L261A
 (Supersedes Service Letter No. L261)
 November 11, 2015

TO: All Owners and Operators of Helicopteres Guimbal Cabri G2 with the following carburetors:

- Lycoming part number (P/N) 61B26215 (AVStar P/N AV10-6110)
- Lycoming P/N 61B26215-L (AVStar P/N AV10-6110)
- Lycoming P/N 61B28159 (AVStar P/N AV10-6500)

SUBJECT: Alternate Carburetor

REASON FOR REVISION: Added alternate carburetor part number

NOTICE: Incomplete review of all the information in this document can cause errors. Read the entire Service Letter to make sure you have a complete understanding of the requirements.

In support of a request from Helicopteres Guimbal, there is an alternative carburetor for the Lycoming O-360-J2A engine installed in the Helicopteres Guimbal Cabri G2. The alternate carburetor is Lycoming P/N 61B28525 (AVStar P/N AV10-6500-1). The alternate carburetor, which can be obtained through any authorized Lycoming distributor, is leaner than carburetor P/N 61B26215 and richer than carburetor P/N 61B28159.

NOTICE: Lycoming carburetor P/Ns 61B26215-L and 61B28159 are no longer available.

Refer to the latest revision of Service Instruction No. SI-1523 for the current listing of carburetors approved for use on corresponding Lycoming engine models.



ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		
04	23	14	11	11	15	1 of 1	A